MiSeq i100 Series v1.0.0.5080 Software Release Notes

©2024 Illumina, Inc. All rights reserved. All trademarks are the property of Illumina, Inc. or their respective owners. For specific trademark

information, see www.illumina.com/company/legal.html.

Introduction

This document details known issues for the MiSeq i100 Series Sequencing System v1.0.0.5080.

For more information on the MiSeq i100 Series Sequencing System, see the MiSeq i100 Series Product Documentation available on the Support Site.

Please contact Illumina Technical Support for additional assistance.

Known Issues

Known issues of the MiSeq i100 Series Software v1.0.0.5080 release.

Component	Summary	Resolution/Workaround
Instrument Software	When users are logged out due to inactivity, users may be navigated back to the Setting Menu instead of the screen they were on when logging back in.	Exist the Setting Menu and navigate to previous screen.
Instrument Software	Instrument software may hang and fail to initialize. This may occur on instruments that are not connected to the network.	• Wait 45 minutes for instrument initialization to timeout. • Click on the 'Restart Application' button on the critical error dialog.
Run Planning	Users will be unable to requeue analysis for sequencing runs performed in Manual mode until a sample sheet is added. Requeue dialog will become unresponsive.	Please add a sample sheet to the run before entering the requeue analysis workflow.
Storage Settings	If USB device is physically ejected without first using the 'Eject' function on the software UI screen, users may not be able to mount the same USB device and software will throw an error.	Please 'Eject' the USB device from the External Storage UI screen before mounting the USB device again.
Storage Settings	Default folder not automatically configured when mounting a new storage device.	Users will need to go to the 'Folder Settings' after mounting storage to configure and select default folder to be used for saving sequencing run data, analysis requeue results, and export log files.
Storage Settings	When mounting NFS storage, the system may throw a 400 error message.	This is a temporary issue and retrying the mount of the NFS system should resolve the error.
Storage Settings	System does not allow spaces in the output folder name.	Rename the folder to exclude any spaces before remounting the folder.

©2024 Illumina, Inc. All rights reserved. All trademarks are the property of Illumina, Inc. or their respective owners. For specific trademark

information, see www.illumina.com/company/legal.html.

Storage Settings	Users will not be able to create new Folders inside the external storage or USB device.	Users will need to create new folders on the external device before mounting to the instrument.
Export Logs	Export Logs screen may fail to load if instrument software crashed unexpectedly.	Power cycle instrument according to instructions in the Product Documentation.
Networking	IP addresses in the following range cannot be used to be assigned to the instrument: 10.42.xx.xx or 10.43.xx.xx	Please assign a different IP address to the instrument.

©2024 Illumina, Inc. All rights reserved. All trademarks are the property of Illumina, Inc. or their respective owners. For specific trademark

information, see www.illumina.com/company/legal.html.

Software Installation Procedure

MiSeq i100 Series Software v1.0.0.5080 is included as part of the MiSeq i100 Series Instrument.

No installation required.

Release History

Revision	Release Reference	Originator	Description of Change
00	1116574	Aneesh Natarajan	Initial release

©2024 Illumina, Inc. All rights reserved. All trademarks are the property of Illumina, Inc. or their respective owners. For specific trademark

information, see www.illumina.com/company/legal.html.