

iSeq™ 100 System Release Notes

Suite Installer v1.4.1

iSeq™ 100 Control Software Server v1.4.1

iSeq™ 100 Control Software Client v1.4.1

Firmware (FW) v1.3.0

Real-Time Analysis (RTA) v2.12.5

Universal Copy Service (UCS) v1.5.4

Local Run Manager (LRM) v2.1.2

Introduction

These release notes detail new features, improvements, and known issues for the iSeq™ 100 Sequencing System software. For more information on the iSeq 100 System, see the *iSeq 100 Sequencing System Guide (document # 100000036024)* on the Illumina website.

The software package includes:

- Suite Installer v1.4.1
- iSeq™ 100 Control Software Server v1.4.1
- iSeq™ 100 Control Software Client v1.4.1
- Firmware v1.3.0
- Real-Time Analysis v2.12.5
- Universal Copy Service v1.5.4
- Local Run Manager v2.1.2

I. iSeq™ 100 Control Software Server, Client and Suite Installer v1.4.1

IMPROVEMENTS

- Updated specification for third image intensity to reduce false positive flow check failures during the pre-run checks

II. Firmware v1.3.0, Real-Time Analysis v2.12.5, Universal Copy Service v1.5.4, Local Run Manager v2.1.2

- No change was made in this release.